$\begin{array}{c} \textbf{11854A} \\ \textbf{ACCESSORY KIT} \\ \textbf{50} \Omega \ \ \textbf{BNC} \end{array}$



JULY 1976



©Copyright HEWLETT-PACKARD COMPANY 1976
1400 FOUNTAIN GROVE PARKWAY, SANTA ROSA, CALIFORNIA, U.S.A.



DESCRIPTION:

The HP Model 11854A 50Ω BNC Accessory Kit contains the components required for interconnections and test setups using a Transmission/Reflection Test Set (HP 8502A), an S-Parameter Test Set (HP 8503A), or a Power Splitter (HP 11850A) for measuring devices having 50Ω BNC connectors. The characteristics of the components in this kit ensure high quality RF measurements of such devices.

PERFORMANCE CHARACTERISTICS:

Return Loss of Adapters: Typically 40 dB up to 1.3 GHz.

CONTENTS:

Qty	Description	HP Part Number
2	Type N Male to BNC Female adapter	1250-1476
2	Type N Male to BNC Male adapter	1250-1473
2	Type N Female to BNC Male adapter	1250-1477
2	Type N Female to BNC Female adapter	1250-1474
1	BNC Male short circuit	1250-0929
1	Storage Case	9211-1582

DIMENSIONS:

WEIGHT:

168 mm wide, 114 mm deep, 51 mm high (6-5/8 in. x 4-1/2 in. x 2 in.)

Net: 1,13 kg (2-1/2 lb) Shipping: 1,59 kg (3-1/2 lb)

CERTIFICATION

Hewlett-Packard Company certifies that this product met its published specifications at the time of shipment from the factory. Hewlett-Packard further certifies that its calibration measurements are traceable to the United States National Bureau of Standards, to the extent allowed by the Bureau's calibration facility, and to the calibration facilities of other International Standards Organization members.

WARRANTY

This Hewlett-Packard instrument product is warranted against defects in material and workmanship for a period of one year from date of shipment. During the warranty period, Hewlett-Packard Company will, at its option, either repair or replace products which prove to be defective.

For warranty service or repair, this product must be returned to a service facility designated by HP. Buyer shall prepay shipping charges to HP and HP shall pay shipping charges to return the product to Buyer. However, Buyer shall pay all shipping charges, duties, and taxes for products returned to HP from another country.

LIMITATION OF WARRANTY

The foregoing warranty shall not apply to defects resulting from improper or inadequate maintenance by Buyer, Buyer-supplied software or interfacing, unauthorized modification or misuse, operation outside of the environmental specifications for the product, or improper site preparation or maintenance.

NO OTHER WARRANTY IS EXPRESSED OR IMPLIED. HP SPECIFICALLY DISCLAIMS THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

EXCLUSIVE REMEDIES

THE REMEDIES PROVIDED HEREIN ARE BUYER'S SOLE AND EXCLUSIVE REMEDIES. HP SHALL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES, WHETHER BASED ON CONTRACT, TORT, OR ANY OTHER LEGAL THEORY.

ASSISTANCE

Product maintenance agreements and other customer assistance agreements are available for Hewlett-Packard products.

For any assistance, contact your nearest Hewlett-Packard Sales and Service Office. Addresses are provided at the back of this manual.

HEWLETT-PACKARD SALES AND SERVICE OFFICES

To obtain servicing information and order replacement parts, contact the nearest Hewlett-Packard Sales and Service Office in HP Catalog, or contact the nearest regional office listed below.

THE UNITED STATES:

CALIFORNIA

3003 Scott Boulevard Santa Clara 95050

GEORGIA

P.O. Box 105005

450 Interstate North Parkway

Atlanta 30348

ILLINOIS

5201 Tollview Dr.

Rolling Meadows 60008

NEW JERSEY

W. 120 Century Road

Paramus 07652

CANADA:

OUEBEC

Hewlett-Packard (Canada) Ltd.

275 Hymus Blvd.

Pointe Claire H9R IG7

EUROPE:

SWITZERLAND

Hewlett-Packard (Schweiz) AG

Chateau Bloc 19

CH-1219 Le Lignon-Geneva

AFRICA, ASIA, AND AUSTRALIA:

Hewlett-Packard Intercontinental 3495 Deer Creek Road

Palo Alto, California 94304

CENTRAL AND SOUTH AMERICA:

Hewlett-Packard Intercontinental 3495 Deer Creek Road Palo Alto, California 94304

